Door Factory Premium 2020 Readme

Information for the RevitWorks Door Factory Premium 2020

By installing the latest version of the Door Factory 2020, any previous versions will be retained (i.e. Door Factory for 2018, 2019 etc.)

Previous Version Default Values

If you have amended the default values that the Door Factory uses, copy the *DefaultValues_I.txt* and *DefaultValues_M.txt* to the new locations as shown.

Copy from C:\Program Data\RevitWorks\Door Factory *(version number)*

Copy to C:\Program Data\RevitWorks**Door Factory 2020**

Previous Version Customised Components

If you have created additional components in previous versions of the Door Factory, we suggest that you copy them to the correct sub-directories under the new Door Factory 2020 Component Directory and then manually upgrade them to Revit 2020. They will then appear in this version of the Door Factory as well.

Please also refer to the Multi User Recommendations Document for instructions on how to use shared network drives for these components.

Revision History

V20.4.4	Curtain panel single hinge door with stop jamb now more robust
	x5 Composite commercial doors added to Parkwood panel library
V20.4.3	Parkwood panel library more robust
V20.4.2	When making multiple doors, panel specific parameters have been corrected
	"Glass Framed with Rail" panel specific dimensions fixed
V20.4.1	Panel specific parameters now carry through to the final family
V20.4.0	Panel specific dimensions for sliding and bifold doors now work as expected
V20.3.9	Corrections to "Clear Opening Width" parameter values
	Corrections to clearance diagram alignments
	When making multiple doors within one session of Revit, panel and handle selections now work as expected
	2-way double door panel and handle materials now come through as expected
	When using "(default) Solid" panels, the specification item now doesn't show the word "(default)"
	Version updater corrected
V20.3.8	Panic bar handle added
	2-way door elevation swings now show as expected
	Licensing module updated
	Trim materials in door family only show when relevant
	Handle backup files now not created during door build
V20.3.7	ADA clearances panel width parameter now links through as expected
V20.3.6	Panel specific dimensions for primary panel on double doors now work as expected
	Rough width formula glitches within the Door Factory removed
V20.3.5	Contained 1+1 slider panel position corrected
	Imperial Parkwood door thickness carried through correctly
V20.3.4	Single leaf door specific dimensions now work as expected
V20.3.3	Building a door from any tab now works as expected
V20.3.2	Licensing module updated

V20.3.1   Single panel doors build as expected when elevation swing is set to "Points to Handle"
V20.3.0   Initial Release

Content that works

www.revitworks.com